STAY SAFE ON FOOT **AROUND FORKLIFTS**

10 MARSON STATES OF AND OTHERS SAFE:





Never walk or work beneath loads on raised forks



Never allow yourself to be lifted on a pallet or on the forks



Never try to steady a load that is slipping off the forks





Never take a lift on a forklift or climb on it to stop it tipping



SAFE

Always keep a safe distance from a working forklift (note the height and width of the load)





Make sure a forklift has stopped before you approach... and always do so from the side



Where available wear hi-vis clothing



Wherever possible use segregated walkways





Help keep walking areas clear and clean up spills, broken pallets, plastic wrap etc

WHEN **RELIABILITY IS EVERYTHING...**

www.mitforklift.com

